



Premium Masking Solutions

Q1® Premium Spray Overall

The overall protects against the general staining that occurs when spraying paint. It prevents contamination of the painted surface with dust and lint. Working with undiluted, concentrated paints or aggressive chemicals requires specific chemical protective clothing. Please refer to the manufacturer's instructions of the products/chemicals to be used, for the the exact requirements of the protective clothing. The fabric is antistatic in accordance with EN 1149-1:2006.



Features

- Hood with elastic band
- Breathable TRIGON back fabric
- Chest pocket with protective flap and Velcro closure
- Comfortable wrist cuffs
- Elasticated ankles
- Available in 6 different sizes
- 2 side pass-through pockets
- Back pocket

Available Colour

Black & yellow

Product Reference

Part#	Size	Pcs/ Case
PSPO_S	Small	20 suits/ box
PSPO_M	Medium	20 suits/ box
PSPO_L	Large	20 suits/ box
PSPO_XL	Extra Large	20 suits/ box
PSPO_2XL	2x Extra Large	20 suits/ box
PSPO_3XL	3x Extra Large	20 suits/ box

Technical Data Sheet

Characteristics

Material: 100% Polyester

CE Certification

Lint and Silicon free

Antistatic EN 1149-1:2006

PSA Cat.1



Premium Masking Solutions

Additional Information**Product Usage:**

Category 1 personal protective equipment (PPE) in accordance with European Directive 2016/425. This product is only intended to protect against minimal risks. An inspection/risk analysis is to be carried out on a case-by-case basis to ensure that the product is suitable for its intended use. There are no hard and fast rules on its suitability; it is the responsibility of the user, as it depends on where the job is being carried out, the materials used, and the concentrations. Further information is available from the manufacturer.

Storage/shelf life:

Store in a dry place in the original packaging at a temperature of 10°C to 30°C. When stored correctly, the product has no expiry date. When used, its actual expiry date cannot be specified because it is determined by its conditions of use. No matter what, an individual risk assessment must be carried out.

Cleaning and care:

The overall can be washed at 40°C or dry-cleaned